



Volkswagen Jetta

Generated on 04/09/2026

VIN: 3VW2B7AJ7HM413896

Body type: Sedan

Fuel: Gasoline

Transmission Type: Automatic

Engine displacement: 1.4 L

Power: 110 kW (148 hp / 150 PS)

Scan for full report



Mileage

⚠ Attention

Long period with no mileage change detected.

Damage

⚠ Attention

We found 3 records for this vehicle.

Title check

⚠ Attention

"Salvage" record found – possible past severe damage.

Commercial use check

✅ No issues found

No records of commercial use found.

Legal status check

✅ No issues found

No financial or legal risk records found.

Theft

✅ No issues found

No theft records found.

+44 Data sources
We checked 1000+ data sources in 48 countries

Photos

We found 4 photos of this vehicle. Scan report QR code to see all.

carVertical Insight

Recorded photos show that this vehicle has sustained visible damage in the past.

08/2023



Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.



No issues found

No records of vehicle being used in irregular manner

Here's what we checked:



Taxi

No evidence of being used as a taxi



Transport

No evidence of being used as a transport vehicle



Rental

No evidence of being used as a rental



Police

No evidence of being used by police



Demo

No evidence of being used as a demo vehicle



Driving school vehicle

No evidence of being used as a driving school vehicle

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.



No issues found

We didn't find any records that the vehicle was stolen.

Here's what we checked:



Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.



Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in 7 countries:



Hungary



Romania



Slovakia



Canada



Slovenia



Italy



Czechia

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.




Summary

- Last known mileage: 1,314 km
- 3 mileage records found



carVertical Insight

It seems this vehicle wasn't being used for a while. There may be a good reason, but it's still useful to learn the facts. Was it damaged? Was there an expensive issue (engine / transmission failure, etc.)? Was there a mileage rollback?



Odometer records

11/2017	32 km
12/2017	1,322 km
08/2023	1,314 km

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.



No issues found

No records about the legal status of this vehicle were found

Legal



Passed technical inspection (MOT)?

No technical inspection records found for this vehicle.



Was it scrapped?

No record of this vehicle being marked as scrapped.

Title check

We checked if the vehicle has a branded title - like "Junk", "Salvage", or "Flood" - which could mean it sustained serious damage or may not be roadworthy.

These are official terms used by US state agencies to flag vehicles with major safety or structural concerns.



Attention

Salvage title found!



We checked 69 title brands across the United States

✓ Record found

Salvage 12/2017

Any vehicle which has been wrecked, destroyed or damaged, to the extent that the total estimated or actual cost of parts and labor to rebuild or reconstruct the vehicle to its pre-accident condition and for legal operation on roads or highways exceeds a jurisdiction-defined percentage of the retail value of the vehicle. The retail value of the vehicle is determined by a current edition of a nationally recognized compilation (to include automated data bases) of retail values. "Salvage Damage or Not Specified" also includes any vehicle to which an insurance company acquires ownership pursuant to a damage settlement, or any vehicle that the vehicle's owner may wish to designate as a salvage vehicle by obtaining a salvage title, without regard to extent of the vehicle's damage and repairs, or any vehicle for which the jurisdiction cannot distinguish the reason the vehicle was designated salvage.

Junk, Salvage or Insurance

✓ Record found

Entity	Details	Export
PROGRESSIVE GROUP OF INS COMPANIES	Insurance Date: 12/10/2017	No
IAA	Junk and Salvage / Vehicle state: Sold Date: 12/10/2017	Yes

Entity	Details	Export
IAA	Junk and Salvage / Vehicle state: To be determined Date: 12/10/2017	No

What these records mean

A record here means a US business reported this vehicle as junk, salvage, or – if the business was an insurer – a total loss. The details show what happened to the vehicle while that business had it.

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



Attention

We found 3 records for this vehicle

Damage records

10/2017

United States



Reported damage


This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Damage reported, parts not listed

Past repair cost estimate

Unknown



Reported damage


This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Damage reported, parts not listed

Past repair cost estimate

Unknown



Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Front body and windshield / Unclassified

Past repair cost estimate

Unknown



View the photos related to this damage event.

[See photos](#) →

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be

related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary


Past repair cost estimate

If the vehicle has reported damage, the past repair cost is estimated based on where the damage was assessed and is shown in that country's currency. This amount may differ from what you'd expect locally. Here's why:
Repair prices vary between countries due to differences in labor rates and parts costs.
The estimate is based on work that is done at official service centers, which are typically more expensive than independent garages.

Market price


We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.



Criteria for market price evaluation:

Make: Volkswagen Model: Jetta Fuel type: Gasoline Year: 2017 Market: Europe



Year	Market price	↘ Lowest market value	↗ Highest market value
● 2020	€11,700	€8,488	€15,161
● 2021	€11,533	€7,800	€15,400
● 2022	€11,800	€9,300	€14,350
● 2023	€12,173	€8,784	€15,376
● 2024	€11,076	€7,694	€14,500
● 2025	€10,910	€7,900	€13,900
● 2026	€9,800	€6,450	€13,055
● 2027	€9,736	€6,408	€12,970
● 2028	€8,810	€5,798	€11,736
● 2029	€7,926	€5,216	€10,558
● 2030	€7,193	€4,734	€9,582
● 2031	€6,251	€4,114	€8,328
● 2032	€5,762	€3,792	€7,676
● 2033	€4,099	€2,698	€5,460

Market price insights



Price trend forecast

This vehicle is expected to lose -58% of its market price over the next 7 years.



Price drop & buying window

The largest drop in market price is expected around 2033, when the vehicle reaches 16 years of age. Buying around this time may offer better value.



Optimal selling timing

Selling before the largest price drop – expected around 2032 or 15 years of age – may help retain more value.



Selling time

Similar vehicles typically sell within 21 days based on recent market data

Note: Forecasts are based on current market trends and historical data. Actual resale value may change due to market shifts, condition, location, or other factors.

Specs

The vehicle's core technical and mechanical build.

 **Summary**
Make sure the vehicle's specs match what the seller told you.

Vehicle specifications



Overview

Make	Model	Fuel type
Volkswagen	Jetta	Gasoline
Model generation	Model year	Manufacturer label
VI	2017	Jetta



Performance & efficiency

Transmission type	Drive type	Engine displacement
Automatic	FWD	1.4 L
Power	Number of cylinders	Number of gears
110 kW (148 hp / 150 PS)	4	6
Torque	Engine code	Engine description
249 Nm	CZTA	1.4T
Powertrain type		
Internal combustion		



Body & dimensions

Body type	Steering wheel placement	Number of seats
Sedan	LHD	5
Number of doors	Wheel size	
4	16 in	

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

i

Summary

Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

0A24 doors 4 Doors Equipped	0AGFront stabilizer Front stabilizer for improved handling
0BGRear stabilizer Rear stabilizer	0ERInstallation differentiation for transmission AQ250 -- vehicle components -- Transmission AQ250 installation differentiation
0FLMexico manufacturing sequence Manufactured in Mexico	0K0Without alternative drive system No Alternative Drive System Installed
0KAWithout decals and emblems Without decals and emblems	0N44-link rear suspension 4-link rear suspension
0NWNameplate set "TSI" Nameplate set with 'TSI' designation	0SCLabels/plates in English Labels and plates on the vehicle in English.
0TAWithout floor mats No Floor Mats Provided	0VMInformation kit in American English Information kit provided in American English
0Y3Cold zones Cold zones for temperature control in specific areas.	0YEWeight range 5 installation control only, no requirement forecast Weight range 5 with installation control only
1A5Fuel system for SI engine Fuel system for SI engine	1ATElectronic stability control (ESC) Electronic stability control (ESC)
1C2Antifreeze up to -35 degree Celsius tolerance up to -40 degree C Antifreeze with tolerance for cold weather	1D0Without trailer hitch Without trailer hitch

1E7 Activated carbon canister ORVR, for intensified

evaporation system, siphoning device for fueling

✦✦ Includes evaporative emission system and fueling siphoning device for emissions compliance

1G6 Space-saving spare wheel

✦✦ Equipped with a space-saving spare wheel

1KQ Disk brakes in rear

✦✦ Disk brakes fitted in the rear

1NY Wheel trims

✦✦ Wheel trims are included in the equipment of this car.

1Q1 Mass damper for steering wheel, 26.5 Hz

✦✦ Mass damper installed for the steering wheel operating at 26.5 Hz

1SA Without additional front underbody guard

✦✦ Additional Front Underbody Guard Not Included

1W0 Without refrigerator/glove compartment cooling system

✦✦ Does not have a refrigerator/glove compartment cooling system.

1XC Multifunction steering wheel

✦✦ Multifunction steering wheel

1ZP Disk brakes in front (Geomet D)

✦✦ Front disk brakes with geomet D

2JG Body-colored bumpers

✦✦ Body-Colored Bumpers

2UA Standard design

✦✦ Standard design

2WA Without additional tires

✦✦ No Additional Tires Provided

3C8 3-point seat belt, center rear with US label

✦✦ Center rear seat belt is a 3-point design with US labeling

1EB Without identification plate

✦✦ Does not have an identification plate

1JA Rear shock absorption, basic version 1

✦✦ Basic Rear Shock Absorption Version 1

1N3 Speed-related variable steering assist (Servotronic)

✦✦ Variable Steering Assist System Installed

1PA Standard wheel bolts

✦✦ Standard wheel bolts

1S1 Tool kit and jack

✦✦ Tool kit and jack

1T0 Without first aid kit and warning triangle

✦✦ Without first aid kit and warning triangle

1X0 Front wheel drive

✦✦ Front Wheel Drive Configuration

1Z0 Initial standard fuel filling

✦✦ Standard Initial Fuel Filling

2G7 Filler neck module 1 with insert

✦✦ Filler Neck Module 1 with Insert

2LF Fuel tank with special material treatment (coextrusion)

with changed protective layer

✦✦ Fuel tank treated with special materials, featuring coextrusion process and changed protective layer

2V1 Dust and pollen filter

✦✦ Dust and pollen filter included

3B7 Child seat anchorage as per Canadian requirements a. ISOFIX child seat system

✦✦ Child seat anchorage system fulfilling Canadian requirements including ISOFIX

3FA Without roof insert (standard roof)

✦✦ No Roof Insert Provided

3G0 Without child seat anchor front (ISOFIX)

Without child seat anchor front (ISOFIX)

3KA Unsplit rear seat bench unsplit, split folding backrest

Rear seat bench that can be folded in split or unsplit configuration

3MF Dilours floor covering with scuff guard

Floor covering with scuff guard protection

3PY Manual height adjustment, for front seats with modified mech. control

Manual height adjustment for front seats with modified mechanical control

3SB Standard seat in front, right

Standard seat in front, right

3W0 Without additional noise suppression measures for passenger compartment

Without additional noise suppression measures for passenger compartment

3ZD 3-point seat belts, outer rear with US label

Outer rear seat belts have 3-point design with US labeling

4B0 Without protective side molding

Without Protective Side Molding

4GQ Windshield in heat-insulating glass

Windshield made of heat-insulating glass

4KC Side and rear windows in heat-insulatingglass

Side and rear windows in heat-insulating glass

4N0 Standard dashboard

Standard dashboard configuration

4QQ 3-point seat belts with tensioner in front and height adjustment, US label

Front seat belts with tensioner and height adjustment feature, complying with US standards

3J1 Height-adjustable head restraints for front seats

Height-Adjustable Head Restraints for Front Seats

3LD Door and side trim panel

Door and side trim panel

3P0 Without bracket for first aid kit and warning triangle

Absence of bracket for first aid kit and warning triangle

3Q6 Three rear head restraints

Three Rear Head Restraints

3TB Standard seat in front, left

Standard seat in front, left

3YQ Door pockets without insert mats

The car does not have door pockets with insert mats.

4A0 Without seat heater

No seat heater

4E2 Tailgate/trunk lid release from inside (electrically)

Electric tailgate/trunk lid release

4K0 Central locking with radio remote control and interior release mechanism

Central locking system with remote control and interior release feature

4L2 Dimming breakaway interior rearview mirror

Dimming breakaway interior rearview mirror

4P1 Rear floor panel module, type 2

Features a rear floor panel module of type 2.

4R4 Power windows with comfort operation andcircuit breaker

Power Windows with Comfort Operation and Circuit Breaker

4U0 Without luggage nets/pockets on backrests

✦✦ No luggage nets/pockets on the backrests

4X3 Side airbag in front, with curtain airbag

✦✦ Front Side Airbag with Curtain Airbag

4ZG Chrome-plated moldings

✦✦ Chrome-Plated Moldings Included

5C1 Body measures for increased safety requirements

✦✦ Safety measures include special body construction

5J0 Without rear spoiler

✦✦ No rear spoiler

5MJ Decorative inserts

✦✦ Includes decorative inserts

5SH Left exterior mirror: flat (US)

✦✦ Flat design for the left exterior mirror

6A0 Without fire extinguisher

✦✦ Without fire extinguisher

6FF Body-colored exterior mirror housings and various add-on parts

✦✦ Body-Colored Exterior Mirror Housings and Add-On Parts

6KE Radiator grille

✦✦ Radiator grille included

6P2 Rear license plate carrier (NAR)

✦✦ Rear license plate carrier for North America

6Q1 Plastic gearshift knob/handle

✦✦ Gearshift knob/handle made of plastic

6XN Exterior mirrors: power-adjustable, separately heated

✦✦ Exterior mirrors are power-adjustable and heated

4UM Driver and front passenger airbag (NAR) with front passenger airbag deactivation(2-stage)

✦✦ Driver and front passenger airbags with deactivation system for the passenger airbag

4Z4 Glove compartment door without light

✦✦ Glove compartment door without light

5A2 Comfort trunk lining

✦✦ Interior trunk lining designed for comfort

5D2 Carrier frequency 315 MHz

✦✦ Uses a carrier frequency of 315 MHz

5K7 Transport protection film (minimum protection) with additional transport protection measures

✦✦ Transport Protection Film with Additional Measures

5RR Right exterior mirror: convex (US)

✦✦ Convex design for the right exterior mirror

5XZ Sun visors with mirror (NAR)

✦✦ Sun visors with mirrors for North American region

6E7 Center armrest in front

✦✦ Center armrest in front

6K0 Without area monitoring system/without autonomous emergency braking system

✦✦ No area monitoring or autonomous emergency braking system

6M0 Without tie down straps/net/pocket

✦✦ No Tie Down Straps/Net/Pocket Included

6PA Plastic hand brake lever handle

✦✦ Plastic hand brake lever handle

6W3 Front license plate carrier (small, NAR)

✦✦ Small, narrow front license plate carrier

7A0 Without CD changer/CD player

✦✦ No CD changer or player included

7AZ Preparation for anti-theft alarm system

✦ Prepared for anti-theft alarm system installation

7CE Emission standard LEV 3/Tier 3 70

✦ Meets Emission Standard LEV 3/Tier 3 70

7G0 Without preparation for VTS (vehicle tracking system)

✦ No preparation for vehicle tracking system

7KK Vehicle class differentiation -160-

✦ Vehicle falls under class designation -160-

7M5 Without protective film for scuff plate

✦ No Protective Film for Scuff Plate Applied

7P0 Without lumbar support in seat backrests

✦ No lumbar support in seat backrests

7Q0 Without navigation device

✦ Without navigation device

7R4 Side turn signals and marker lights (turn signals with white lens)

✦ Features side turn signals and marker lights with white lens for enhanced visibility

7Y0 Without lane change assist

✦ Without lane change assist

8GU Alternator 140 A

✦ 140 A Alternator Installed

8K4 Separate daytime running lights -- NAR --

✦ Separate daytime running lights

8N4 Windshield wiper intermittent control with potentiometer (four speeds)

✦ Windshield wiper with four-speed control

8RH 4 speakers (passive)

✦ Vehicle has 4 passive speakers

7B5 12-volt socket(s)

✦ 12-volt socket(s) for charging electronic devices

7E0 Without heat accumulator/auxiliary heater

✦ Without heat accumulator/auxiliary heater

7K6 Indirect tire pressure monitoring system

✦ Indirect tire pressure monitoring system equipped on the vehicle

7L3 Without start/stop system without regenerative braking

✦ No start/stop system and regenerative braking

7N2 Spectacle storage compartment/bracket

✦ Spectacle storage compartment/bracket

7PA Platform group class 1

✦ Platform group class 1

7QA Without CD/DVD for navigation

✦ Without CD/DVD for navigation

7X0 Without park distance control

✦ No park distance control feature present

8G0 Without light control

✦ Without light control

8IE Halogen twin headlamps and separate LED daytime running lights

✦ Halogen twin headlamps with separate LED daytime running lights for improved visibility

8L6 "diversity" window antenna

✦ Radio antenna with diversity reception capability

8Q0 Without headlight range adjustment

✦ The vehicle does not have a headlight range adjustment feature.

8S0 Without reading light

✦ Does not have a reading light feature.

8SB Tail lamp assembly w/ dark colored lens

✦✦ Tail lamp assembly with dark colored lens

8TA Without rear fog lamp

✦✦ Does not include a rear fog lamp

8WA Without front fog lamps

✦✦ No Front Fog Lamps

8Y0 Single-tone horn

✦✦ Equipped with a single-tone horn.

9AB Manually controlled air conditioning system

✦✦ Manually controlled air conditioning system

9M0 Without auxiliary heater/fuel-fired parking heater

✦✦ No Auxiliary Heater/Fuel-Fired Parking Heater Installed

9Q1 Multi-function display/on-board computer

✦✦ Multi-function display and on-board computer

9U0 Without brake pad wear indicator

✦✦ No brake pad wear indicator

9Z0 Operating voltage 12 V

✦✦ Standard Operating Voltage 12 V

A60 Category 0

✦✦ Category 0 - Not specified

AV2 Driving on the right (NAR)

✦✦ Driving on the right side of the road

B0D Component parts set, complying with vehicle type for
USA (without California), various parts

✦✦ Includes various components that comply with vehicle
regulations for the USA, excluding California

C23 Operating permit, alteration

✦✦ Operating permit for alterations has been granted.

8T2 Cruise control system (CCS) electronic

✦✦ Electronic cruise control system

8W0 Without washer fluid level indicator

✦✦ No Washer Fluid Level Indicator

8X0 Without headlamp washer system

✦✦ Without Headlamp Washer System

8Z6 Hot country

✦✦ Vehicle designed for hot climate conditions

9JF Non-smoker's package (NAR)

✦✦ Includes a non-smoker's package

9P7 Visual and acoustic seat belt reminder, electric contact in
buckle

✦✦ Seat belt reminder system with visual and auditory alerts

9T0 Without heated washer nozzles

✦✦ No heated washer nozzles

9WC Without "Multimedia" in vehicle

✦✦ No 'multimedia' in vehicle

9ZX Mobile phone interface

✦✦ Mobile phone interface included.

A8B Basic equipment

✦✦ Basic equipment

AW0 Version (low)

✦✦ Base version of the vehicle

BU1 Legal requirements for USA 1 States without CARB
requirement

✦✦ Legal requirements specific to certain US states that do not
have CARB emissions standards

CM1 Steel wheels 6.5J x 16

✦✦ 16-inch steel wheels

DG6 4-cylinder SI engine 1.4 I/110 kW TSI base engine is

TL9/TL1/TK8/TW8/TL8/T28

✦✦ 4-cylinder SI engine 1.4 L/110 kW TSI base engine is
TL9/TL1/TK8/TW8/TL8/T28

EA0 Without follow-on warranty

✦✦ No Follow-On Warranty Included

EM0 Without driver alert system

✦✦ Without driver alert system

FC0 Without customized installation

✦✦ No customized installation

G18 Shock absorption in front

✦✦ Front shock absorption system

GP1 Vehicles with special upgrade measures

✦✦ Vehicles with special upgrade measures

I6W MIB2 Entry PQ radio NAR

✦✦ MIB2 Entry PQ radio system for North American region

K8B Notchback

✦✦ Notchback body style

KK1 Refrigerant R134a

✦✦ Uses refrigerant R134A

KN1 With trim panel

✦✦ Includes trim panel.

L06 Suspension range 06 installation control only, no

requirement forecast

✦✦ Suspension Range 06 Installation Control Only, No
Requirement Forecast

N7A Seat trim covers in fabric

✦✦ The seats in this car are upholstered with fabric material.

NZ0 Without call feature

✦✦ No call feature

E0A No special edition

✦✦ Standard Edition, No Special Version

EL0 Without online service

✦✦ No online service

F0A No special purpose vehicle, standard equipment

✦✦ Standard Equipment, No Special Purpose Vehicle

FM3 Variant

✦✦ Variant

G1A 6-speed automatic transmission

✦✦ 6-speed automatic transmission

H4B All-season tires 205/55 R16 H (NAR)

✦✦ All-season tires with dimensions 205/55 R16 H for North
American region

J1L Battery 280 A (60 Ah)

✦✦ Battery with 280A capacity (60 Ah)

KA1 With rear view camera system (type 1)

✦✦ Rear View Camera System (Type 1)

KL1 LED license plate lighting

✦✦ LED license plate lighting

KP4 With additional switch

✦✦ Equipped with an additional switch

L0L Left-hand drive

✦✦ Left-Hand Drive Configuration

NY0 Standard battery/alternator capacity

✦✦ Standard battery/alternator capacity

QD3 Nameplate for sales name

✦✦ Nameplate for sales name

QG0 Without service interval prolongation Service interval prolongation not included	QH0 Without voice control Without Voice Control
QI7 Service indicator 10 000 miles or 1 year(fix) Service indicator set at intervals of 10,000 miles or 1 year	QJ1 Chrome package Chrome package
QN0 Without drawers under front seats Without drawers under front seats	QQ0 Without add. lights (interior lighting) Without additional lights (interior lighting)
QR0 Without compass/road sign display/ dynamic road sign display Excludes compass, road sign display, and dynamic road sign display features.	QV0 Without TV reception/digital radio reception No TV reception/digital radio reception
TL1 4-cylinder SI engine 1.4 I unit 04E.A 4-cylinder SI engine 1.4 L unit 04E.A	U5C Instrument cluster, mph speedometer USA Instrument cluster displaying speed in miles per hour for the USA
UG0 Without hill start assist/hill descent control/comfort driving assist No hill start assist, hill descent control, or comfort driving assist	UI5 Electric interface for external use, USB (iPod-capable) Electric interface for external use, USB (iPod-compatible)
V0R BRIDGESTONE tires Bridgestone tires equipped	VC0 Without remote-controlled garage door opener No remote-controlled garage door opener
VF0 Standard pedal cluster Standard Pedal Cluster	VL0 Standard pedestrian protection measures Standard pedestrian protection measures
X9A Equipment options subset for USA Equipment options tailored as a subset for the USA	

Timeline

7 records found

The timeline of records for this vehicle

10/2017  United States Damage detected  We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.
11/2017  United States Ownership changed An ownership change or document update was recorded for this vehicle. Some changes may be formal, such as end-of-lease transfers.

11/2017  United States

Title changed

A title change was recorded for this vehicle. This may be due to ownership changes, technical updates, or document revisions.

12/2017  United States

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

12/2017  United States

Title changed

A title change was recorded for this vehicle. This may be due to ownership changes, technical updates, or document revisions.

08/2023  United States

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

08/2023  United States

Listed for sale

A listing record shows this vehicle was put up for sale. Sometimes, the listing country may differ from the vehicle's actual location.



+44

Data sources

We checked 1000+ data sources in **48 countries**

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Based on this report:

☐

Check the repair quality

Past photos show this car was damaged. Now you need to see if the repairs were done properly – or if corners were cut.

☐

Compare the damaged areas in the photos with how those panels look now.

☐

Look for signs of poor repair work like paint overspray on seals or uneven panel gaps.

☐

Check for long-term inactivity issues

Cars that sit unused for extended periods develop hidden problems with batteries, brakes, seals, electronics, and rubber parts. Storage damage won't show up in records.

☐

Test the battery – long-term storage drains or damages it.

☐

Inspect for seized brakes or flat-spotted tires from long-term parking.

☐

Check the engine bay for rodent damage (chewed wires are common in outdoor storage).

Do these checks before buying a car:

☐

Get a professional inspection

An expert mechanic can spot hidden issues you might miss. Here's what to do next:

☐

Book a pre-purchase inspection at an independent or authorised service

☐

Ask the mechanic to check key systems: engine, brakes, suspension, electronics

☐

Request written notes or a report of any issues found

☐

Ask for service records

Service records show how well the car has been looked after. Here's what to do next:

☐

Ask the seller for the car's service book or maintenance records

☐

Check for regular oil changes, filter replacements, and timing belt work

☐

Note any missing or overdue services

☐

Check if the mileage matches

Make sure the mileage in this report matches the car's odometer readings. Here's what to do next:

☐

Check the odometer reading against the mileage in the report

☐

Watch for signs of tampering (worn pedals, suspicious dashboard fixes)

☐

Ask the seller about any differences

☐

Take a real test drive

A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

☐

Drive on different road types: highway, city traffic, and bumpy or uneven surfaces

☐

Listen for strange noises or vibrations

☐

Pay attention to handling and comfort



Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:



Search for similar cars online (same make, model, year, mileage)



Compare asking prices



Look at car condition and equipment



Use this info to negotiate with the seller