

DS

VR1JCYHZRKY039244

2019

Diesel

Automatic

SUV

Grey

Generated on 23/10/2026

Scan for full report



Damage

⚠ Attention

We found 1 record for this vehicle.

Commercial use check

✓ No issues found

No records of commercial use found.

Mileage

✓ No issues found

Last recorded mileage: 119,613 km.

Legal status check

✓ No issues found

No financial or legal risk records found.

Theft

✓ No issues found

No theft records found.

Emissions

✓ No issues found

Low CO₂ emission rating: 100 g/km.



+44

Data sources

We checked 1000+ data sources in **48 countries**

Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.



No issues found

No records of vehicle being used in irregular manner

Here's what we checked:



Taxi

No evidence of being used as a taxi



Transport

No evidence of being used as a transport vehicle



Rental

No evidence of being used as a rental



Police

No evidence of being used by police



Demo



No evidence of being used as a demo vehicle

Driving school vehicle

No evidence of being used as a driving school vehicle

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.



No issues found

We didn't find any records that the vehicle was stolen.

Here's what we checked:



Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.



Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in **8 countries**:



Slovakia



Slovenia



Hungary



Italy



Romania



Czechia



Canada



Sweden


Mileage

We checked if the mileage looks accurate or if it may have been tampered with.



Summary

- Last known mileage: 119,613 km
- 2 mileage records found



Odometer records

05/2019	11 km
07/2023	119,613 km

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.



No issues found

No records about the legal status of this vehicle were found

Legal



Passed technical inspection (MOT)?

No technical inspection records found for this vehicle.



Was it scrapped?

No record of this vehicle being marked as scrapped.

Damage

Has this vehicle been damaged in the past? What was the value of the damages?




Attention

We found 1 record for this vehicle

07/2023

France



Exterior affected

Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Front / Windshield

Glass

Past repair cost estimate

€501 – €750

Possible Cause

Glass Damage

Description

Not specified

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Past repair cost estimate

If the vehicle has reported damage, this estimate is based on repair prices in the country where the damage was assessed, converted to your local currency.

Why it may differ from repair prices in your country:

Hourly rates and parts prices vary between countries.

The estimate is based on official service center prices. These are usually higher than independent garage prices.

Emissions

We analysed how much CO₂ this car model typically produces and what taxes or fees may apply.



carVertical Insight

This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

CO₂ emissions

100 g/km Class: **A**



Specs

The vehicle's core technical and mechanical build.



Summary

Make sure the vehicle's specs match what the seller told you.

Vehicle specifications



Overview

Make	Fuel type	Manufacture year
DS	Diesel	2019
Category	Type approval	
M1	e2*2007/46*0601*05	



Performance & efficiency

Transmission type	Drive type	Engine displacement
Automatic	FWD	1.5 L
Power	CO ₂ emissions	Emissions standard
96 kW (129 hp / 131 PS)	100 g/km	Euro 6
Transmission name	Powertrain type	
ATNG8	Internal combustion	



Body & dimensions

Body type	Steering wheel placement	Color
SUV	LHD	Grey
Unladen weight	Gross weight	
1,428 kg	2,050 kg	

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

 **Summary**

Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

01109830781799 Identification code: 9830781799	381515439 88 1 0943
511015/05/2019 Manufacturing date: 15th May 2019	AACOT26AUTOMATIC AIR CONDITIONING Automatic air conditioning
ABSMIB28ACTIVE BLIND SPOT MONITORING Active blind spot monitoring system	ACAEA27ALTERNATOR CLASS 18 180 AMP Alternator class 18 with 180-amp output
ACLU14ANALOGUE CLOCK Analog clock	ACNLU29ANALOGUE CONNECTED NAVIGATION Analog navigation system with connected features
AFHRYJ374-WAY ADJUSTABLE FRONT HEAD RESTRAINT Front headrest with 4-way adjustment	AFYCF20AIRCON FLUID 1234 YF Air conditioning fluid 1234 YF
AG85ATNG8 Automatic Transmission and NG8 package	AHAOT29AUTOMATIC HEADLAMP ADJUSTMENT Automatic headlamp adjustment
ALWTRGUI52ACOUSTIC LAMINATED WINDSCREEN + TOUGHENED REAR GLASS Acoustic laminated windscreen	ASOOTLSOT56AUTOMATIC SWITCHING ON OF THE LIGHTS+AUTOMATIC SWITCHING Automatic switching on of the lights

ATG8P17 ATN8 TYPE GEARBOX

✦✦ ATN8 type gearbox

BCCA9 BLACK CAP

✦✦ Black Cap

BFYT13 Body fittings

✦✦ Description of the body fittings and exterior features of the vehicle

BWTPW19 BUMPER WITHOUT TRIM

✦✦ Bumper without trim

CAFPTL29 CENTRAL ARMREST FLOCKED + PVC

✦✦ Central armrest flocked and PVC

CEHOB31 CHROME+BODY-COLOURED EXT HANDLE

✦✦ Chrome and body-colored exterior handles

CMPE23 Component manufacturers

✦✦ Information about the manufacturers of various vehicle components

CSACSE41 CHEST-PELVIS SIDE AIRBAG+RR CHEST+CURTAIN

✦✦ Safety features include chest-pelvis side airbags, rear chest protection, and curtain airbags

CTDS30 CONDENSER 19,3DM2 THICKNESS 12

✦✦ 19.3dm2 thick condenser

DASBA23 DOUBLE ACCESSORY SOCKET

✦✦ Double accessory socket

DCMWLLVP53 DRIVER+PASSENGER CONCEALABLE MIRROR WITH LED LIGHTING

✦✦ Driver and passenger concealable mirror with LED lighting

DEFVP53 DRIVER+PASSENGER ELECTRIC FOLDING+DIODE+MAR+MEMORY+EL

✦✦ Driver and passenger seats with electric folding, diode lights, memory function, and electronic adjustment

AWAOH22 ALLOY WHEEL ASSEMBLY 1

✦✦ Alloy wheel assembly 1

BCFBGCRBBL75 BODY COLOUR FR BUMPER+GLOSS BLACK GRILLE+BODY COLOUR RR BUMPER+PAINTED BEAD

✦✦ Body-colored front bumper, gloss black grille, body-colored rear bumper, and painted bead details

BLEEETY33 BATTERY L3 760 70AH EFR 760 EN EF

✦✦ 760 70Ah L3 battery

C038 1500 CM3

✦✦ 1500 cm3 engine

CCDU14 COLD COUNTRIES

✦✦ Cold countries specification

CEMGVE28 CURVED EXTERIOR MIRROR GLASS

✦✦ Curved exterior mirror glass

CMPM12 CARPET MAT 1

✦✦ Carpet mat set

CSG13 PASSENGER CAR

✦✦ Passenger car

CVLPMC30 COMMERCIAL VEHICLE LEVEL 2 PSA

✦✦ Level 2 commercial vehicle specification by PSA Group

DCCS20 DS 7 CROSSBACK (X74)

✦✦ DS 7 Crossback model

DDR622 DV5RC 96KW 1.5L DIESEL

✦✦ DV5RC 96 kW 1.5L diesel engine

DETIEE32 DIRECT EXCHANGER TURBO INJECTION

✦✦ Direct exchanger turbo injection system

DFPFLVF39 DRIVER + FR PASSENGER FOOTWELL LIGHTING

✦✦ Footwell lighting for driver and front passenger

DGDSG22 DIESEL GRADE DA/DE/DE+

✦✦ Diesel engine with grade DA/DE/DE+

DSS2 DS

✦✦ Dual-zone climate control

DSWMCFAVS60 DRIVER'S SEAT WITH MEMORY

CONTROL+CUSHION FRONT ADJUSTMENT

✦✦ Driver's seat with memory control and front cushion adjustment

DTEYE14 DV TYPE ENGINE

✦✦ Diesel engine type

E0418 e2*2007/46*0601*05

✦✦ Compliance with European vehicle safety standards

EC10 Electrical

✦✦ Electrical

EEECOE32 EURO 6.2 ENGINE EMISSION CONTROL

✦✦ Engine meets Euro 6.2 emission standards

EPGPPT25 EVL - PLATINUM GREY PAINT

✦✦ EVL - Platinum Grey paint

ESPCO28 ELECTRONIC STABILITY PROGRAM

✦✦ Electronic stability program

EVTECOV43 EURO 6.2 VEHICLE TECHNICAL EMISSION

CONTROL

✦✦ Vehicle meets Euro 6.2 technical emission control standards

DFVS19 DRIVER'S FOOTREST

✦✦ Special footrest for the driver's comfort

DIPWLIL41 DIGITAL INSTRUMENT PANEL 29 WARNING

LAMPS

✦✦ Digital instrument panel with 29 warning lamps

DSTBELSVS56 DRIVER'S SEAT TILTING BACK ELECPNE

LUMBAR SUPPORT+MEMO

✦✦ Electrically tilting driver's seat with lumbar support and memory function

DTDDTC31 DGT TOUCHSCREEN+12" DFT DISPLAY

✦✦ Digital touchscreen display with 12 inches

DWIN15 2 DRIVEN WHEELS

✦✦ 2 driven wheels

ECDHACI34 ELECTRIC CONTRL DRIVERS HEIGHT ADJ

✦✦ Electric control for driver's height adjustment

EE4 "FE"

✦✦ Includes an element labeled as 'FE'.

ELASG44 PASSENGER ELECTROPNEUMATIC LUMBAR

ADJUSTMENT

✦✦ Passenger's electropneumatic lumbar adjustment

EPIP25 ENGINE POWER 96KW - 300NM

✦✦ Engine power output: 96kW - 300Nm

EUCPNOA42 EUROPEAN UNION CONSTRUCTOR'S PLATE +

NRE

✦✦ European Union constructor's plate

FABSNNR39 FR ANTI-ROLL BAR STIFFNESS 32500 NM/RAD

✦✦ Front anti-roll bar stiffness is 32500 NM/RAD

FACDFEF42 2-SPEED FAN 140W AERO COMPACT DYNAMIC

FLAP

✦✦ 140W two-speed fan with dynamic flap

FDRXAR25 FINAL DRIVE RATIO 15 X 58

✦✦ Final drive ratio 15 × 58

FGLSWFLA46 FULL GRAIN LEATHER STEERING WHEEL FULL
4-SPOKE

✦✦ Full grain leather steering wheel with 4-spoke design

FPSHAEHAFSCAN97 FRONT PASSENGER SEAT HEIGHT
ADJUSTER ELECTRIC HEIGHT ADJUSTMENT+ELECTRIC FRONT
SEAT CUSHION ANGLE

✦✦ Electric height adjustment for front passenger seat with
electric front seat cushion angle

FROSNE32 FRONT-REAR RADAR OBSTACLE SENSOR

✦✦ Front-rear radar obstacle sensor

FSTFRSSA41 4 FR SPEAKERS (2 TW + 2 FR)+2 RR SPEAKERS

✦✦ 4 front speakers and 2 rear speakers system

FWSNRSNH37 FRONT WHEEL SENSOR NON-SIGN RR
SIGNED

✦✦ Front wheel sensor non-sign rear signed

GLID20 GRAINED LEATHER "57"

✦✦ Grained leather interior with a pattern called '57'

GTRX20 Gearbox Transmission

✦✦ Details about the gearbox and transmission system of the
vehicle

ICDTEA31 INTERNAL COMBUSTION DRIVE TRAIN

✦✦ Internal combustion engine drive train

IFE017 Interior fittings

✦✦ Details about the interior fittings and features of the vehicle

FBIB12 FAMILY BADGE

✦✦ Family badge

FESCCFASG51 PASSENGER'S FR ELEC SEAT CTRL +
CUSHION FRONT ADJ

✦✦ Passenger's front electric seat control with front cushion
adjustment

FIEMME42 FRAMELESS INTERIOR ELECTROCHROMATIC
MIRROR

✦✦ Frameless interior electrochromatic mirror

FRMRT12 FR + RR MATS

✦✦ Front and rear mats

FSLP18 Fuel supply-Engine

✦✦ Information related to fuel supply and the engine of the
vehicle

FWBWRSN134 FRONT WIPER BLADE WITH RAIN SENSOR

✦✦ Front wiper blade with rain sensor

GIEL19 General information

✦✦ Overview and general information about the vehicle

GTDR12 GOOD TERRAIN

✦✦ Good terrain capability

HNA13 HORNS-HARMONY

✦✦ Horns-harmony

IDOUWLIC51 INDIRECT DETECTION OF UNDER-INFLATION
WITH LOCATION

✦✦ Indirect detection of under-inflation with location system

IRTL14 INITIALE RANGE

✦✦ Initial Range feature

ITACPTH37 IHX TECHNOLOGY AIR CONDITIONING PIPES

✦✦ IHX technology air conditioning pipes

ITUEN29 INDEPENDENT TELEMATIC UNIT 3S

✦✦ Independent telematic unit

LBBB8 LED BULB

✦✦ LED bulb lighting

LDTN15 LEFT-HAND DRIVE

✦✦ Left-hand drive

LGLKLGTR40 LEATHER GEAR LEVER KNOB + LEATHER
GAITER

✦✦ Leather gear lever knob and gaiter

LSCGBLSR44 LED STORAGE COMPARTMENT + GLOVE BOX
LIGHTING

✦✦ LED storage compartment and glove box lighting

MALLOR32 MONOCHROME AMBIENCE LED LIGHTING

✦✦ Monochrome ambience LED lighting

MLAI16 METALLIC LACQUER

✦✦ Metallic lacquer paint

MSH9H27 433.92 MHZ SUPER HETERODYNE

✦✦ 433.92 MHz signal frequency

NAMA17 NORMAL ATMOSPHERE

✦✦ Normal atmosphere conditioning

NHSHT15 NON HEATED SEAT

✦✦ Non-heated seats

OLTVT43 PREVENTION+CORRECTION OF LATERAL
TRAJECTORY

✦✦ System for preventing and correcting lateral trajectory

ITFNT20 18 INCH TYRE FITMENT

✦✦ 18-inch tyre fitment

KK4 00CK

✦✦ Wheel Size 00CK

LDDTR23 LEATHER DECOR DASHBOARD

✦✦ Dashboard with leather decoration

LFCLFN36 LED FRONT FOGLAMPS + CORNERING LAMPS

✦✦ LED front fog lamps with cornering function

LPDPEPSPE47 LOW POWER DOUBLE PINION ELECTRIC
POWER STEERING

✦✦ Low power electric power steering with double pinion

MADUA26 MANUAL AIRBAG DEACTIVATION

✦✦ Manual airbag deactivation feature

MCL13 Miscellaneous

✦✦ Miscellaneous details and additional information about the vehicle

MMMO22 2ND MINOR MODIFICATION

✦✦ 2nd minor modification

NALMA26 NORMAL + AUTOMATIC LOCKING

✦✦ Normal and automatic locking system

NFTWLTPS43 NON-PRESSURISED FUEL TANK WITH
LOCATING TAB

✦✦ Non-pressurised fuel tank with locating tab

NSMS17 NORMAL SUSPENSION

✦✦ Normal suspension

Q3015 10 Q3AR 0074890

RABDRT28 REAR ANTI-ROLL BAR DIAM 18.5

✦✦ Anti-roll bar located in the rear of the vehicle with a diameter of 18.5 units

REBAIO32 RADIATOR 28DM2 EP: 18 BRAZED ALU

✦✦ Radiator with 28dm2 EP: 18 brazed aluminum

RFIEO25 RESERVOIR FILTER INTERIOR

✦✦ Reservoir filter interior

RGLATFATSWSG54 RAISED GEAR LEVER AT THE FLOOR + AT THE STEERING WHEEL

✦✦ Raised gear lever at the floor + at the steering wheel

RNT5135 235/55 R18 100V NON-REINFORCED TYRE

✦✦ Standard non-reinforced 235/55 R18 100V tires

SCFTS33 SEAT CUSHION+BACK 2/3-1/3 FOLDING

✦✦ 2/3-1/3 folding rear seat cushion and backrest

SIAWL126 STYLE2 18 INCH ALLOY WHEEL

✦✦ 18-inch alloy wheels with Style2 design

SLF5 SHELF

✦✦ Shelving system

SPEENR39 STANDARD PROVISION ELECTRICAL EQUIPMENT

✦✦ Standard provision electrical equipment

SSDA12 STTD STARTER

✦✦ Standard starter

SSWCA24 SPACE-SAVING SPARE WHEEL

✦✦ Space-saving spare wheel

SVV6 S.U.V.

✦✦ Sport utility vehicle

TDWGTD33 TINTED + DARK-TINTED WINDOW GLASS

✦✦ Tinted + dark-tinted window glass

RASLUT25 REGULATOR AND SPEED LIMIT

✦✦ Regulator and speed limiter system

REEACL30 R3 ECO ELECTRICAL ARCHITECTURE

✦✦ R3 eco electrical architecture

RFSCRT37 RETRACTABLE FLOOR STORAGE COMPARTMENT

✦✦ Retractable floor storage compartment

RHARA24 REAR HEADREST ADJUSTABLE

✦✦ Adjustable rear headrests

RVABOV31 RIVOLI VARIOUS ADDITIONAL BADGE

✦✦ Additional badge for Rivoli model

SGIKER24 SPEED GRADUATION IN KM/H

✦✦ Speed graduation in km/h

SIE14 SOCIETE (OVSA)

✦✦ Organization Version (OVSA)

SOBKBOA31 SET OF BADGE KEYS + BACK-UP KEY

✦✦ Set of badge keys + back-up key

SPS26 Suspension-Steering-Brakes

✦✦ Information regarding the suspension, steering, and brakes of the vehicle

SSPBPS29 SIMPLE STANDARD PEDAL BRACKET

✦✦ Standard pedal bracket

STAGTE34 STT TYPE 8-SPEED AUTOMATIC GEARBOX

✦✦ 8-speed automatic gearbox

SWG NR25 STANDARD WINDSCREEN GLASS

✦✦ Standard windscreen glass

TLPSCDNT49 THIN LATERAL/SIDE PROTECTORS+BODY SILL CHROMED DS

✦✦ Thin lateral and side protectors with chromed body sill accents

TRTRI15 TRI RADIO TUNER

Three-band radio tuner

VAWHSPIT42 VARIANT ASSOCIATED WITH HIGH SEAT POSITION

Variant associated with high seat position

VFDDTA33 VENTILATED FRONT DISCS/REAR DISCS

Ventilated front discs/rear discs

WAHHT27 WITHOUT ADDITIONNAL HEATING

Without additional heating

WAPHT24 WITHOUT ADDITIONAL PULSE

Without additional pulse equipment

WBCMHT31 WITH BATTERY CHARGE MEASUREMENT

With battery charge measurement

WCHT14 WITHOUT CLUTCH

Without clutch mechanism

WCHT21 WITHOUT CIGAR-LIGHTER

Without cigar-lighter

WDELRHT40 WITHOUT DETACHABLE EXTERIOR LASHING RING

Without detachable exterior lashing ring

WEAHT27 WITHOUT EQUALISER AMPLIFIER

Without equalizer amplifier

WEPQP18 W/O EQUIPMENT PACK

Without equipment pack

WETPHT25 WITHOUT EXHAUST TAIL PIPE

Without exhaust tail pipe

WFFCHT23 WITHOUT FUEL FILLER CAP

Without fuel filler cap

UPBR11 3 USB PORTS

3 USB ports

VCIE23 Vehicle characteristics

Details regarding the vehicle's characteristics and specifications

WAHD27 WITH "OBD" AUTO-DIAGNOSTICS

With OBD auto-diagnostics

WAHT15 WITHOUT ASHTRAY

Without ashtray

WAWIFARHT39 WITHOUT ANCHORAGE WITH ISOFIX FR AND RR

Without ISOFIX anchorages

WCDHT20 WITHOUT COMPACT DISC

Without compact disc player

WCHT18 WITHOUT CONVERSION

Without conversion

WCSHT16 WITHOUT CAB SEAT

Without cab seat

WDFWDHT36 WITHOUT DIESEL FILTER WATER DETECTOR

Without diesel filter water detector

WEOEXU30 W/O EXHAUST OUTLET EMBELLISHER

Without exhaust outlet embellisher

WERFTN30 WESTERN EUROPE RADIO FREQUENCY

Western Europe radio frequency

WEUNN24 W/O ENGINE UNDERSHELDING

Without engine undershielding

WHCGCHA30 WITH HEATER CASING GAS CIRCUIT

With heater casing gas circuit

WHEEE18 W/O HELP EQUIPMENT

✦✦ No help equipment provided

WHWEL18 W/O HEADLAMP WIPER

✦✦ Without headlamp wiper

WLHT13 WITHOUT LABEL

✦✦ Without label

WLPHT26 WITHOUT LATERAL PROTECTORS

✦✦ Vehicle does not have lateral impact protectors

WNCSHV36 WITH NAVIGATION SYSTEM COLOUR SCREEN

✦✦ With navigation system color screen

WOLIIE23 W/O OIL LEVEL INDICATOR

✦✦ No oil level indicator

WPFACHL37 WITH POLLEN FILTER + ACTIVATED CARBON

✦✦ With pollen filter and activated carbon

WPUBHT29 WITHOUT PROTECTION UNDER BODY

✦✦ No protection under the body

WRPPRS27 W/O RR PASSENGER PROTECTION

✦✦ Without rear passenger protection system

WRSAHA22 WITH REAR SEAT ARMREST

✦✦ With rear seat armrest

WSASHE26 WITH STEERING ANGLE SENSOR

✦✦ With steering angle sensor

WTHT14 WITHOUT TOWBAR

✦✦ Without towbar

WVLRHT32 WITHOUT VEHICLE LOAD RECOGNITION

✦✦ No vehicle load recognition system

WWTHR21 WITH WARNING TRIANGLE

✦✦ Comes with a warning triangle for added safety

WHMHA18 WITH HEATER MATRIX

✦✦ With heater matrix

WKEASHY28 WITH KEYLESS ENTRY AND START

✦✦ Keyless entry and start system

WLPHT21 WITHOUT LICENCE PLATE

✦✦ Without license plate

WMLHR16 WITH MIRROR LINK

✦✦ With mirror link feature

WOCHT24 WITHOUT ON-BOARD CHARGER

✦✦ No on-board charger

WPEFHR29 WITH PARTICLE EMISSION FILTER

✦✦ With particle emission filter

WPTAHT29 WITHOUT POWER TRAIN ACOUSTICS

✦✦ Without powertrain acoustics

WRPDHT30 WITHOUT RR PASSENGER DETECTION

✦✦ Without rear passenger detection system

WRPVAVPHA49 WITH REAR PANORAMIC VISUAL ASSISTANCE VISIO PARK1

✦✦ With rear panoramic visual assistance system

WRWHT19 WITHOUT ROOF WINDOW

✦✦ Without roof window

WSASSHO27 WITH STOP AND START STARTER

✦✦ Stop and start starter system

WTPAHT30 WITHOUT THEFT PROTECTION ALARM

✦✦ Without theft protection alarm

WWHF9 WITH WIFI

✦✦ With WiFi connectivity

Timeline

4 records found

The timeline of records for this vehicle

04/2019	France	First registration A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.
05/2019	Country unknown	Manufactured This vehicle's manufacturing date has been recorded. The listed country may reflect a production or registration location.
07/2020	France	Registered A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.
07/2023	France	Damage detected We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.



+44

Data sources
We checked 1000+ data sources in 48 countries

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Do these checks before buying a car:

☐

Get a professional inspection

An expert mechanic can spot hidden issues you might miss. Here's what to do next:

☐

Book a pre-purchase inspection at an independent or authorised service

☐

Ask the mechanic to check key systems: engine, brakes, suspension, electronics

☐

Request written notes or a report of any issues found

☐

Ask for service records

Service records show how well the car has been looked after. Here's what to do next:

☐

Ask the seller for the car's service book or maintenance records

☐

Check for regular oil changes, filter replacements, and timing belt work

☐

Note any missing or overdue services

☐

Check if the mileage matches

Make sure the mileage in this report matches the car's odometer readings. Here's what to do next:

☐

Check the odometer reading against the mileage in the report

☐

Watch for signs of tampering (worn pedals, suspicious dashboard fixes)

☐

Ask the seller about any differences

☐

Take a real test drive

A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

☐

Drive on different road types: highway, city traffic, and bumpy or uneven surfaces

☐

Listen for strange noises or vibrations

☐

Pay attention to handling and comfort

☐

Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

☐

Search for similar cars online (same make, model, year, mileage)

☐

Compare asking prices

☐

Look at car condition and equipment

☐

Use this info to negotiate with the seller